

INSPECTION SERVICES AND ENGINEERING CERTIFICATION

AB: 780.870.1547 **SK:** 306.250.9294 **Head Office Mail:** P.O. Box 10524 Lloydminster, AB T9V 3A6

INSPECTION REPORT

EQUIPMENT LOCATION:	Lloydminste	er, Alberta	NDT P	ROCEDURE#:		INSP-001	
EXAMINATION COVERAGE:	RANDOM:	5% 10	25%	50%	75%	100%	Х
ACCEPTANCE CRITERIA:	CSA W59	ISO 9927-1		AODC RP	2.0	OTHER:	
INSPECTION METHOD:	VT X UT	MT WET F	LOURESCENT	MT WET	BLACK	X MT DRY	RED X
EQUIPMENT INFO:	BLACK LIGHT N	1AKE - INOVA	LIGHT METER	R # 1822158	MAG	COIL # RC1-30	120121

CLIENT:	K&S Power Tongs	UNIT/RIG:	KS151
EQUIPMENT:	'YC' Slip Type Elevator	MAKE/MODEL:	BVM/3 ½"-7'
RATING:	75 Ton	SERIAL NUMBER:	20343

EQUIPMENT PHOTOS



INSPECTION RESULTS

ACCEPTABLE:	X REJECTED:	DATE OF INSPECTION:	February 1, 2019
TECHNICIAN:		COMMENTS:	
CANCGSB. AGO TO SOME T	DN: cn=Tyson C. McLean, o=Index NDT Inspections Ltd., ou, email=tyson @indexndt.ca, c=CA	REPAIRS:	

QUALITY ASSURED INSPECTIONS FOR QUALITY ASSURED BUSINESSES

Except as provided herein, Index NDT Inspections Ltd. makes no warranty, express or implied with respect to the mechanical or other conditions of the equipment inspected by us. Index NDT Inspections Ltd. shall only be responsible in the event of damage resulting directly from their inspection, and in no event, shall the liability of Index NDT Inspections Ltd. exceed the cost of inspection." Our organization assumes only the responsibility of locating defects in the inspected components and welds made accessible at the time of inspection. All equipment should be cleaned to allow access to all welds and critical components. It is of the utmost importance that the unit's owner be aware that excessive coating over 10 mils can servely mask the detection of discontinuities while utilizing standard inspection techniques. We are not responsible for the mechanical or other conditions assembled condition except at customer's request.

HINCLUSION P-POROSITY IUC-INTERNAL UNDERCUT EUC-EXTERNAL UNDERCUT S-SLAG C-CRATOR IP-INCOMPLETE PENETRATION NF-NON-FUSION CR-CRACK PH-PIN HOLE D-DISCONTINUITY



CERTIFICATE OF COMPLIANCE

CLIENT: K & S Power Tongs

UNIT: KS151

EQUIPMENT: 'YC' Slip Type Elevator

 MANUFACTURER:
 BVM

 MODEL:
 3 ½"-7"

 RATING:
 75Ton

 SERIAL #:
 20343

LOCATION: Lloydminster, AB **INSPECTION DATE:** February 1, 2019

CONDITIONS OF USE:

- 1. Identification and rating to be permanently affixed in a visible location
- 2. Visually inspect equipment prior to each use
- 3. Maintain equipment in good condition

CERTIFICATION:

Index NDT Inspections Limited performed a VISUAL AND MAGNETIC PARTICLE inspection on the above-mentioned OVERHEAD EQUIPMENT after it was cleaned and disassembled. All observations have been recorded and are disclosed in the Index NDT Inspections Ltd. report for the OVERHEAD EQUIPMENT with the serial #20343. The scope of this certificate is limited to the inspection of item's structural condition at the time of inspection and does not imply a review of the equipment's design or it's associated capacity rating. The capacity noted above reflects the original equipment manufacturer's maximum capacity rating and may be reduced by operating conditions, regulatory requirements and the use of auxiliary equipment that has a lower capacity rating.

The undersigned Engineer reviewed all the inspection reports and has issued this certificate after all repairs (if any) were completed. In the undersigned engineer's opinion, the OVERHEAD EQUIPMENT #20343 may be returned to service and operated within the original manufacturer's specifications. The equipment owner must provide the OEM's operating instructions with the equipment and maintain the OEM's identification and capacity markings. If OEM cannot be obtained, certified replacements must be obtained.

VALIDATION:

This certification covers the above-mentioned unit for a period of 500 operating days from the "inspection date" listed above, as per CAODC Recommended Practice 2.0, or until the unit is damaged by handling, transportation or operation.

Reviewed By:



Brad Nordell 2019.02.05 14:33:03 -07'00'