

INSPECTION SERVICES AND ENGINEERING CERTIFICATION

PHONE: 780.870.1547 EMAIL: operations@indexndt.ca Head Office Mail: P.O. Box 10524, Lloydminster, AB T9V 3A6

INSPECTION REPORT

EQUIPMENT LOCATION:	Lloydminster, Alberta			a	NDT PROCEDURE#:				INSP-001			
EXAMINATION COVERAGE:	RANDOM:		5%	10%	T	25%	50%	75%	T	100%	X	\neg
ACCEPTANCE CRITERIA:	CSA W59 X ISO 9927-1		927-1	1	CAODC RP 2		2.0	.0 OTHER:			\neg	
INSPECTION METHOD:	VT X U	X UT MT WET FLOURESCENT MT WET BLA			BLACK	-	MT DRY	BED I	X			
EQUIPMENT INFO:	BLACK LIGHT MAKE - INOVA LIGHT METER # 1822158 MAG COIL # RC1-30120121				1							

CLIENT:	K&S Power Tongs	UNIT/RIG:	KS 412
EQUIPMENT:	Casing Elevator	MAKE/MODEL:	BJ/4 1/2"
RATING:	65 Ton	SERIAL NUMBER:	H12618

EQUIPMENT PHOTOS



INSPECTION RESULTS

ACCEPTABLE:	X REJECTED:		DATE OF INSPECTION:	June 18, 2021
TECHNICIÁN:		COMMENTS:		
LEVEL II		Dr	SPAIDS:	
M.F 2082	125 1	H	EPAIRS:	

QUALITY ASSURED INSPECTIONS FOR QUALITY ASSURED BUSINESSES

Except as provided herein, Index NDT inspections Ltd. makes no warranty, express or implied with respect to the mechanical or other conditions of the equipment inspected by us. Index NDT inspections Ltd. shall only be responsible in the event of damage resulting directly from their inspection, and in no event, shall the liability of Index NDT inspections Ltd. exceed the cost of inspection. "Our organization assumes only the responsibility of locating defects in the inspectad components and walds made accessible at the time of inspection. All equipment should be cleaned to allow access to all walds and critical components it is of the utmost importance that the unit's owner be aware that accessive coating over 10 mils can severely mask the detection of discontinuities while utilizing standard inspection techniques. We are not responsible for the mechanical or other conditions assembled condition events at customers's requirest.



CERTIFICATE OF COMPLIANCE

CLIENT:

UNIT:

EQUIPMENT:

MANUFACTURER:

MODEL:

RATING:

SERIAL #:

LOCATION:

INSPECTION DATE:

K & S Power Tongs

KS 412

Casing Elevator

BJ

4 1/2"

65 Ton H12618

Lloydminster, AB

June 18, 2021

CONDITIONS OF USE:

- 1. Identification and rating to be permanently affixed in a visible location
- 2. Visually inspect equipment prior to each use
- 3. Maintain equipment in good condition

CERTIFICATION:

Index NDT Inspections Limited performed a VISUAL AND MAGNETIC PARTICLE inspection on the above-mentioned OVERHEAD EQUIPMENT after it was cleaned and disassembled. All observations have been recorded and are disclosed in the Index NDT Inspections Ltd. report for the OVERHEAD EQUIPMENT with the serial #H12618. The scope of this certificate is limited to the inspection of item's structural condition at the time of inspection and does not imply a review of the equipment's design or it's associated capacity rating. The capacity noted above reflects the original equipment manufacturer's maximum capacity rating and may be reduced by operating conditions, regulatory requirements and the use of auxiliary equipment that has a lower capacity rating.

The undersigned Engineer reviewed all the inspection reports and has issued this certificate after all repairs (if any) were completed. In the undersigned engineer's opinion, the OVERHEAD EQUIPMENT #H12618 may be returned to service and operated within the original manufacturer's specifications. The equipment owner must provide the OEM's operating instructions with the equipment and maintain the OEM's identification and capacity markings. If OEM cannot be obtained, certified replacements must be obtained.


VALIDATION:

This certification covers the above-mentioned unit for a period of 500 operating days from the "inspection date" listed above, as per CAODC Recommended Practice 2.0, or until the unit is damaged by handling, transportation or operation.



Permit # 14408





Digitally signed by David Bernardin -- P.

Eng. - APEGA

Date: 2021.06.18

16:04:32 -06'00'

INSPECTION SERVICES AND ENGINEERING CERTIFICATION

PHONE: 780.870.1547 EMAIL: operations@indexndt.ca Head Office Mail: P.O. Box 10524, Lloydminster, AB T9V 3A6